## No. 8023 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	·
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	and the second of the second o	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATE	TRAL TO WALL OF BUILDING SERVED.	
<u> 1900-yılın de de engile e</u>	en e	•
and the second of the second o	and the second of the second o	
interpretation of the second o	en de la composition de la composition La composition de la	
	and the control of th	
SIGNED	FILED AT ENGINEER'S OFFICE	
INSPECTOR FOR CIT		

Milson

## $N^{\circ}$ 8023

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, Jacquery 2
RECEIVED OF Prichard 7	
FOR WHICH PERMISSION IS GRANTED	Gray
TO TAP Sanitary SE	WER ON THE East
of bile III. S. AVE.	PE OF STREET Hard Sunface
THE PREMISES BEING LOT NO. 2324	HOUSE NO. 920
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC OF THE DEPARTMENT OF PUBLIC SERVICE.	E No. 2323, DULY PASSED BY THE CITY COUNCIL, ANI
Name of Contractor Thanks	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.