

215

Nº 8029

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-11-68

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 329

SIZE OF PIPE USED 4"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR R. FRANKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature]
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS ROOTS HAD GROWN IN CLEAN OUT AT THIS POINT C.O.
TAKEN OUT REPLACED WITH STRAIGHT PIPE

Nº 8029 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, March 13

RECEIVED OF Richard Franks

FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED Tom Lestoff

TO TAP Sanitary

SEWER ON THE West

OF 6th St. S.W.

AVE.
ST. TYPE OF STREET Hard Surface

THE PREMISES BEING LOT NO. 9361

HOUSE NO. 339

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Richard Franks

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**