## Nº 8038

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3 3 5 8	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO23 45	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  114 EAST OF MH 9 DEET
WAS LATERAL AT CHES	Bob in the second of the secon
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR JOE & Toe
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
The state of the s	
	- Commence of the control of the con
e la time i di tivi essa fina i la colo la comuzione di	such and the Committee of the Appendix of the Committee o
	The state of the s
i de la companya da l	
ing min man of from manage	11A'
	114,
SIGNED INSPECTOR FOR CI	TY STATE OF THE ST

## $\mathbf{N}$ ? 8038

## PERMIT TO TAP SEWER

Massillon	OHIO, africk	22
RECEIVED OF JAC AJAC VOLE		FEE OF S
FOR WHICH PERMISSION IS GRANTED DA. Fred La	ice the	
// · · · · · · · · · · · · · · · · · ·	South	
of Glamial Pallerry AVE. TYPE OF STREET	Chips Le	e.C.
	HOUSE NO. 22	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, ANI OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR LOS & Jac Lafe

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.