Relay Nº 8041

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

C- 11/18

DATE INSPECTED 4-26-68 HOUSE NO. 514	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? VES IN Prof. WAS ATTACHED TO MAIN. NO	NAME OF CONTRACTOR R. FY 37K5
SHOW BY DIAGRAM RELATION OF LATE	
	m 2th pass
	DARK P.02.
I I sha	Trunk
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE

Nº 8041

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

MASSILLON, OHIO PRIL 26
RECEIVED OF Rudard Franks PEE OF \$ 5.
FOR WHICH PERMISSION IS GRANTED I when light
TO TAP Sanctary SEWER ON THE Gart
of 19 dd. 11 W. AVE. TYPE OF STREET Chip II deal
THE PREMISES BEING LOT NO. 5090 HOUSE NO. 514
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR FLATILES

Note: This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.