## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	DATE INSPECTED _ 5-3/-68	IF SO HOW AND LOCATION FROM
	HOUSE NO. 4/3	DISTANCE FROM FIRST MANHOLE OLD HOUSE LAT,
	SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
	WAS LATERAL AT CURB? VES	
		NAME OF CONTRACTOR OF MARKS
	SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SERVED.
	<b>1</b>	2 3
		2 NO
	ang kitaban sakan sa sa sa sakar sa <del>Malaba</del> n sa titub	TO THE RESIDENCE OF THE PROPERTY OF THE PROPER
		SIDEWALK
γ.	SIGNED	FILED AT ENGINEER'S OFFICE
-	V INSPECTOR FOR CITY	The second of th
	REMARKS	

Nº 8048

## OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

		MASSILLON	ч, Оню <u>, <i>III а</i></u>	ey 20 1
RECEIVED OF	MASCAL		D	FEE OF \$ 5.
FOR WHICH PERMISSION	IC CDANTED	Can Il	tack	
- Janile		. SEWER ON THE	Acec	th
Lines-Con	May E.	VE.	Marie	Lugare
THE PREMISES BEING LO	0 277	7	HOUSE NO.	1/7 3
	CORDANCE WITH ORD	INANCE No. 2323,		THE CITY COUNCIL, AND
Name of Contractor	Mucae ?	Marko		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.