

Relay

Nº 8064

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-3-68

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 420


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED _____

WAS LATERAL AT CURB? 113 VERT

WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR HOLDEN ROAD

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED ROV. L. T. HAM INSPECTOR FOR CITY FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 8064

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO,

AUG. 1

68

RECEIVED OF

HOLDERBAUM

FEE OF \$

50

FOR WHICH PERMISSION IS GRANTED

MATHEWS

TO TAP

REPAIR SAN.

SEWER ON THE

EAST

OF

420 3RD ST. N.E

AVE.

ST. TYPE OF STREET

PAVED

THE PREMISES BEING LOT NO.

698

HOUSE NO.

420

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

HOLDERBAUM

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.