Nº 8068

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO. 288	FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEFTH
WAS LATERAL AT CURB?	NAME OF CONTRACTOR Hold GR GAUM
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
N 4 RELAY	TOURE SIDE WALK
SIGNED WILLIAM SIGNED INSPECTOR FOR CI	FILED AT ENGINEER'S OFFICE

Kelay

PERMIT TO TAP SEWER

RECEIVED OF MICKE HARDWALLEN FEE OF \$ 5. FOR WHICH PERMISSION IS GRANTED MISS. THESE
The state of the s
TO TAR NORMANY SEWER ON THE GOLD
OF
THE PREMISES BEING LOT NO. 7595 HOUSE NO. 888

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AN

OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR / Hallewatern

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.