

✓
Nº 8073

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-20-68

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 517

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

L N



MAIN LINE

SIGNED

William Hammer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Kelley
Nº 8073

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO. *August 20*
RECEIVED OF *Racene Marks* FEE OF \$ *5.*
FOR WHICH PERMISSION IS GRANTED *Mrs. Agatha Ventura*
TO TAP *Sanitary* SEWER ON THE *West*
OF *3rd St. W. E.* AVE. TYPE OF STREET *Hard Surface*
THE PREMISES BEING LOT NO. *735*, HOUSE NO. *517*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Marks*

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.