

Relay
Nº 8077 ✓

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

9-13-68

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

1214

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

IN PROP

YES

WAS ATTACHED TO MAIN

No

NAME OF CONTRACTOR

HOLDERBAUM DRA

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N

CLEAN
OUT

5
7
10
40

SIGNED

W. Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Relay
Nº 8077

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO

September 17

RECEIVED OF

Halderbaum

FEE OF \$

5.

FOR WHICH PERMISSION IS GRANTED

Mrs. Walzuck

TO TAP

Sanitary

SEWER ON THE

East

OF

Apache St. S. E.

AVE.

ST. TYPE OF STREET

East Grand

THE PREMISES BEING LOT NO.

12778

HOUSE NO.

1214

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Halderbaum

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**