No. 8080 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-23-68	IF SO HOW AND LOCATION FROM	
HOUSE NO.		
SIZE OF PIPE USED 67	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 12 N. 05 M	8'D.
WAS LATERAL AT CURB?	and a company of the	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR A. GLICK &	A. DIAN
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED, $arphi'$	
	0,c 3/D	
	5-0	-
HAT STANDED FRANK OF DESCRIPTION DESCRIPTION	The second of the second secon	
	The state of the s	
SIGNED INSPECTOR FOR CIT	FILED AT ÉNGINEER'S OFFICE	

Nº 8080

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO, Sufference 23
RECEIVED OF any Calhaun FEE OF \$ 5.
FOR WHICH PERMISSION IS GRANTED Dtto Ramband
TO TAP Sanitary SEWER ON THE WEST
OF 21 St. T. W. AVE. TYPE OF STREET Chip & Lea
THE PREMISES BEING LOT NO. 10517 , HOUSE NO. 35
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, ANI
OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR LICENSE

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.