FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

DATE INSPECTED 10-1-68	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 2065		WESTOS	My DEI
WAS LATERAL AT CURB? VES	NAME-OF CONTRACTOR	WM	HECK
SHOW BY DIAGRAM RELATION OF LATES	RAL TO WALL OF BUILDING SERVED	·	
		5/16/10	
	t de la companya de La companya de la co	اما	
N			
SIGNED INSPECTOR FOR CIT	↑ 77′ → FILED AT ENGINEE		
Residence of the second	。 《1916年 - 1918年 - 1918年 - 1918年 新疆	The same of the same	,

Nº 8081

PERMIT TO TAP SEWER

·	Massillon,	OHIO Septem	hie 26.
RECEIVED OF R.C.	Dominick	To the second	FFF OF S
FOR WHICH PERMISSION IS GRANTED	Mapan J	Lungma	
TO TAP Sanctry	SEWER ON THE	Sout	ch
Tumont ala S;	AVE.	Hard	wace
THE PREMISES BEING LOT NO. P.L.	0.h. 264		65
WORK TO BE DONE IN ACCORDANCE WIT			CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVI	GE.	•	
NAME OF CONTRACTOR	Hick		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.