

1077 JER
N^o 8084

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 843

SIZE OF PIPE USED 4" / 11

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



PN

CURB

0' 11" 7' 0"
18' 11" 10' 0"

SIGNED [Signature]
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS STACK BROKEN PIE PLACED USED 12' 05"

Relay
Nº 8084 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SE.
PERMIT TO TAP SEWER

MASSILLON, OHIO, OCT. 8

RECEIVED OF RICHARD FRANKS FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED ROBERT LOOMIS

TO TAP SAN SEWER ON THE WEST

OF 1ST ST. N.E. AVE. ST. TYPE OF STREET PAVED

THE PREMISES BEING LOT NO. 9722, HOUSE NO. 843

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR RICHARD FRANKS

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.