FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-9-68	FIRST MANHOLE DOWN STREAM WY 12 10 15ASTOFM 9
HOUSE NO. 553	<u>.</u>
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE COMES MAN TO DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	nga nganggang nganggang nganggang nganggang
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR A. DIANA
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
en e	The state of the s
And the second s	
I Par	AMVALE 1=70'-
SIGNED INSPECTOR FOR CI	FILED AT ENGINEER'S OFFICE
REMARKS	· · · · · · · · · · · · · · · · · · ·

N 8085

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

RECEIVED OF ROBER	-IKITS GAL	FEE OF \$60.
FOR WHICH PERMISSION IS GRANTED.		
TO JAP SAM	SEWER ON THE	South
or Aranale a.c. 71.6.	AVE. _ST. TYPE OF STREET	Chip & Seal OUTS10
THE PREMISES BEING LOT NO. 19352		OUSE NO. 731 553
WORK TO BE DONE IN ACCORDANCE WITH OF	RDINANCE No. 2323, DU	LY PASSED BY THE CITY COUNCIL, ANI
OF THE DEPARTMENT OF PUBLIC SERVICE.		ET TABLE ST THE CIT COUNCIL, AND

NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.