## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 8091 AND SIGNED WHEN RETURNED

DATE INSPECTED 11-4-68 IF SO HOW AND LOCATION FROM
HOUSE NO DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED CURB LINE AND DEPTH CURB LINE AND DEPTH
WAS LATERAL AT GURB?
WAS ATTACHED TO MAIN NAME OF CONTRACTOR WM HECK
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
$ \underline{}_{10'} $ $ \underline{}_{7'} $
N- 75
didness of the control of the control of the control of the control of the state of
V CLRE
I ( ) I
SIGNED FILED AT ENGINEER'S OFFICE
REMARKS

## Nº 8091

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

A Lung

	MASSILLON, OHIO COLUMN 23
RECEIVED OF Wal Hick	FEE OF \$ 5-
FOR WHICH PERMISSION IS GRANTED Lugue	f 7. Heimann
Non Trul	VER ON THE Earl
OF Warcen St. 71. W. AVE. TYP	E OF STREET Chip & Seal
THE PREMISES BEING LOT NO. 4693-1169	4 , HOUSE NO. 720
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	ENO. 2323, DULY PASSED BY THE CITY COUNCIL, ANI
of the Department of Public Service.	
NAME OF CONTRACTOR	<u></u>

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.