Nº 8093 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-10-69	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2430	
SIZE OF PIPE USED 611	DOWN STREAM TO DITCH AT 2/5 5, 05 M/ 7 DEET
WAS LATERAL AT CUEBY YES	POP - Land Transport of the second of
WAS ATTACHED TO MAIN. No. 19	NAME OF CONTRACTOR WM HIECK
SHOW BY DIAGRAM RELATION OF LATER	
the state of the s	3,6
	702
SIGNED V. Vatham	2151 FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CITY	

REMARKS

Nº 8093

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

11-0

M	ASSILLON, OHIO Catalun	29
RECEIVED OF Harry Selly		FEE OF \$ 5. !
FOR WHICH PERMISSION IS GRANTED Harry	Gelf	
FOR WHICH PERMISSION IS GRANTED	77	
JOHAP Samlan SEWER	ON THE WATER	
fallet my 5 " art 1910"	£	7° 7
of Mindains Of 18:11 7/ AVE. TYPE	OF STREET Chip 4	liel_
THE PREMISES BEING LOT NO. 1390 H	, HOUSE NO. 24	130
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO	O. 2323, DULY PASSED BY THE	CITY COUNCIL, AN
OF THE DEPARTMENT OF FUBLIC SERVICE,		
NAME OF CONTRACTOR MESSE		
The second secon		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.