No. 8094 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 16-36-6	· P
DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 6/8	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT
Prop Vac	CURB LINE AND DEPTH
WAS LATERAL AT GURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR WM HECK
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED.
	7 10 1
	70
e leste aphanique (Normalista)	and the control of th
	and the first term of the property of the prop
	A second to the
	12 660
signed of athon	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR	CITY The second of the second
REMARKS	

Nº 8094

PERMIT TO TAP SEWER

	MASSILLON, OHIO Solsten 29
RECEIVED OF Many Sell	7 FEE OF \$ 5.
FOR WHICH PERMISSION IS GRANTED NAMY	Self
TO TAP Samutary SE	WER ON THE BAST
of 25 th. 81.71. AVE. TY	
THE PREMISES BEING LOT NO. 18914	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC	E No. 2323, DULY PASSED BY THE CITY COUNCIL, AN
Herh	
NAME OF CONTRACTOR	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.