


N^o 8097

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-9-68IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 607SIZE OF PIPE USED 4"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____WAS LATERAL AT CURB? YESWAS ATTACHED TO MAIN NONAME OF CONTRACTOR M. H. HOLDER BAC

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED S. Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Kelley

Nº 8097 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO *November 5*

RECEIVED OF *M. R. M. Corp.* FEE OF \$ *5.*

FOR WHICH PERMISSION IS GRANTED *M. R. M. Corp.*

TO TAP *Sanitary* SEWER ON THE *West*

OF *1st St. S. W.* AVE. ST. TYPE OF STREET *Hard surface*

THE PREMISES BEING LOT NO. *O. G. 31* HOUSE NO. *607*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Kelderman*

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.