


Nº 8098

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-21-68IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 530SIZE OF PIPE USED 4"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____WAS LATERAL AT CURB? NoWAS ATTACHED TO MAIN YESNAME OF CONTRACTOR R. FRANKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N
6'

SIGNED

V. Latham

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

6' OF STACK OK LAID 40' OF NEW 4" SEWER to

Relay

Nº 8098

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *November 15* 19*15*

RECEIVED OF *Richard Franks* FEE OF \$ *5.00*

FOR WHICH PERMISSION IS GRANTED *Richard Jacobs*

TO TAP *Sanitary* SEWER ON THE *North*

OF *Cherry Rd. W.C.* AVE. ST. TYPE OF STREET *Hard Surface*

THE PREMISES BEING LOT NO. *878*, HOUSE NO. *530*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Franks*

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.