Nº 8099

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-20-68	IF SO HOW AND LOCATION FROM
HOUSE NO. 788	FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 90 NorTHOFM 8 DIE E
WAS LATERAL AT CHIRE? VES	Prop. STEINBACH
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
	8b
1	
1 Les	
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE - 90' -
INSPECTOR FOR CIT	ร้างที่ และ และ ซาซาซุ (ค.ศ. 25 กุล 12 มี ค.ศ. 25 การยั <mark>นมา</mark> กา
REMARKS	

N 9099

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, Wanten 20
RECEIVED OF Ful Stic	nhach FEE OF \$5.1
FOR WHICH PERMISSION IS GRANTED RAKEL	t Riggle
TO TAP Sanitary SE	WER ON THE Fact
of Carcuit Jane 16. AVE. TY.	PE OF STREET Chip & Scale
THE PREMISES BEING LOT NO. 12513	HOUSE NO. 788

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Stientach & rearating.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.