

Nº 8102

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12-28-68

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 18

SIZE OF PIPE USED 4"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? —

WAS ATTACHED TO MAIN —

NAME OF CONTRACTOR DIANA

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hamm
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Delay

Nº 8102

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO.

Dec 26

RECEIVED OF

A. J. Diano

FEE OF \$

5.00

FOR WHICH PERMISSION IS GRANTED

Robert J. Shultz

TO TAP

REPAIR LATERAL

SEWER ON THE

NORTH

OF

BURTON ST. N.E

AVE.
ST. TYPE OF STREET

BLACKTOP

THE PREMISES BEING LOT NO.

7828

HOUSE NO.

18' BURTON

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

A. J. Diano

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.