

Nº 8106

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 2-11-69

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 214

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? PROP YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR R. MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N —————



13' 1" x 3' 0"

SIGNED _____

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

REPLACED ONE PIPE @ BUILDING IN SIDEWALK

Relay

Nº 8106 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 2-11 1

RECEIVED OF Rocco Marks FEE OF \$ 5.

FOR WHICH PERMISSION IS GRANTED TO REPAIR

TO TAP Sanitary SEWER ON THE EAST
OF N. ERIE AVE. ST. TYPE OF STREET SIDEWALK

THE PREMISES BEING LOT NO. 59 HOUSE NO. 214 N. ERIE

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. H. Marks

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**