## Nº 8108 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

· · · · · · · · · · · · · · · · · · ·	SO HOW AND LOCATION FROM
HOUSE NO. 1222	
DO DO	WN STREAM TO DITCH AT 75 5, 65 M 7/2 D
WAS LATERAL AT GURB? VES	
WAS ATTACHED TO MAIN NA	AME OF CONTRACTOR ALICK
SHOW BY DIAGRAM RELATION OF LATERAL	TO WALL OF BUILDING SERVED.
	12
· · · · · · · · · · · · · · · · · · ·	the state of the s
the second of the second superior and	40
	30°B, 1
0 0	
	75
SIGNED INSPECTOR FOR CITY	/ Production Filted AT ENGINEER'S OFFICE
REMARKS	(42) A second of the second

## Nº 8108

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

0	MASSILLON, OHIO, February 11
Lacob la	lick 5
RECEIVED OF Lacabe	Allick FEE OF S.
FOR WHICH PERMISSION IS, GRANTED	
Sanitary	ER ON THE East
OFSEWE	
THE PREMISES BEING LOT NO. 12305	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR Albert Slice	É

Note: This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.