## Nº 8115 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-14-69 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 274  DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED 611 DOWN STREAM TO DITCH AT 187 WEST & M 7 DIETE
WAS LATERAL AT CURB? YES
WAS ATTACHED TO MAIN NAME OF CONTRACTOR A. (5/10/k)
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
70 54 no
$\int \int -187$
SIGNED FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CITY
REMARKS

## Nº 8115

## OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

· · · · · · · · · · · · · · · · · · ·	MASSILLON, OHIO, April 8 1
RECEIVED OF amus Elica	k 5:
FOR WHICH PERMISSION IS GRANTED AMES	1. Mariay
Sanitary	VER ON THE Worth
6 := 1/	E OF STREET Chip & hal
THE PREMISES BEING LOT NO. 118174 11818	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Albert Schick

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.