

Nº 8117

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-15-69

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

18' S. OF M.H. 3' N. OF

HOUSE NO. 424 FORD

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

18' S. OF M.H. 3.5' DEEP

SIZE OF PIPE USED 4"

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR BLICK & WEAVER

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

424

35' DEEP @ TIE IN
C.B.
TIED INTO
OF GORGE

INSTEAD
MAIN LINE
C.B. LATERAL
OR
PIT

SIGNED J. McDevitt
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS House Drains Tie INTO STORM SEWER
Tied INTO LATERAL INSTEAD OF MAIN LINE

Storm

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

Nº 8117

MASSILLON, OHIO, *April 9*

RECEIVED OF *Glick & Weaver*

FEE OF \$ *5.00*

FOR WHICH PERMISSION IS GRANTED *Glick & Weaver*

TO TAP *Storm*

SEWER ON THE *East*

OF *Ford St. 71.71.*

AVE.
ST.

TYPE OF STREET *Canal*

THE PREMISES BEING LOT NO. *12153*

HOUSE NO. *424*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Albert Glick*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**