Nº 8120 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4.1/-69	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2326	
A contract of the contract of	DISTANCE FROM FIRST MANHOLE PROWNSTREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? YES	The state of the s
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR THOMPSON
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
and the state of the	→ 19, 14-
	10 53.0 N
Palle	4-29'-4-237'
SIGNED 100 100 FOR CIT	다 마스트 프로마 스크 FILED AT ENGINEER'S OFFICE Y 당하하다 나 한 기계가 한테로 된 (아니다 나라 한 사람들이

Nº 8120

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	Manager	and	ril	10
RECEIVED OF Reluct L. Than	MASSILLON,			5. e
FOR WHICH PERMISSION IS GRANTED SETTINGS	c Bld	es. Ob.	D.D.	utter)
Janetary Services	WED ON THE	7/	with	
Nagen Irail 71.6. AVE. TYP	PE OF STREET.	dea	nel	
	,			6
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC				

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Many con

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.