8123

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	·	
		HOW AND LOCATION FROM T MANHOLE DOWN STREAM
	HOUSE NO. 1/23-27-31-39	CURB@10 TH ST
	DOWN	N STREAM TO DITCH AT 247 7 0 15 15 70
	WAS LATERAL AT CURBI	and the control of the control of the state of the state of the control of the co
	WAS ATTACHED TO MAINNAM	ME OF CONTRACTOR WM HISCK
	SHOW BY DIAGRAM RELATION OF LATERAL TO	O WALL OF BUILDING SERVED.
,	1 3'D	DAC A
	3'STARTED	30000 mg
L.	Lincoln SWAY EAST	K 247 - S3' - CUI
	SIGNED INSPECTOR FOR CITY	ALL CONTROL OF THE DAT ENGINEER'S OFFICE

Nº 8123

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	MASSILLON, OHIO, April 30		
RECEIVED OF WILL Trick	5		
//	ulquare FEE OF 5		
FOR WHICH PERMISSION IS GRANTED			
TO TAP Sanitary SEW	ER ON THE South		
of h.) k. E. AVE. ST. TYPI	OF STREET Hard Luface		
THE PREMISES BEING LOT NO. 486-87-88	1123 / 1131 HOUSE NO. 1137 1139		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	No. 2323, DULY PASSED BY THE CITY COUNCIL, AND		

Note: This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.