Nº 8128

REMARKS

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INS	and the second second second	FIRST MANHOLE DOWN STREAM	NYE 99'S	SOUTHOSHY!
HOUSE NO	0. 1506-137	DISTANCE FROM FIRST MANHOLE		-
SIZE OF P	IPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		·
WAS LATE	ERAL AT CURBI NO	one de la companya de la Maria de Maria. La		
WAS ATTA	CHED TO MAIN /ES	NAME OF CONTRACTOR	M. Ho	LDER BAUM
SHOW BY		TERAL TO WALL OF BUILDING SE	<u> </u>	30 K90 (B)
· ···· · · · · · · · · · · · · · · · ·		4 ,	Satisfaction of the control of the c	E CXC WALE
V Asian Januari (Maria Asian)		¥ 27. oktober – kolegeptory <mark>,</mark> oktob		S K
ter and the second	en e			/n6
	CO C D	<u></u>	7,4	/ \ /\$
SIGNED	V. Vatha		GINEER'S OFFICE	· :
	INSPECTOR FOR	ury Par Page 1 de Habita de Sant		



PERMIT TO TAP SEWER

N° 8128

NO RELAY

MASSILLON, OHIO, MAY 22

NEW SEWER

Ho

HOLDER BAUM

OF 5.0

OR WHICH PERMISSION IS GRAN

DANITAR

SEWER ON THE 57

5 2 5 Q

LHIPLOEAL

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR HOLDER BAUM

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.