

Nº 8130 ✓

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-23-69

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 2757-~~8~~

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 45' 7' DIA

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR A. G. Lick

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 8130

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO

MAY 22

RECEIVED OF

GLICK & WEAVER

FEE OF

5.

FOR WHICH PERMISSION IS GRANTED

TO TAP

SANITARY

SEWER ON THE

SOUTH

OF

SCHULER

AVE.
ST. TYPE OF STREET

GRAVEL

THE PREMISES BEING LOT NO.

121464 12147

HOUSE NO.

2757

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

ALBERT GLICK

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.