Nº 8131

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED IF SO HOW AND LOCATION FROM IF SO HOW AND LOCATION FROM
HOUSE NO. 725 W MAIN
SIZE OF PIPE USED C" UP DOMEN STREAM TO DITCH AT 92 E. OF MY C/2 DEE
WAS LATERAL AT CURB? YES
WAS ATTACHED TO MAIN NO NAME OF CONTRACTOR HOLE
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
$ \underline{\xi} $
1 = 60' 7 90 MEND
Poly WALBASH
SIGNED FILED AT ENGINEER'S OFFICE
DEMARKS

Nº 8131

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO- LUNC 3	1
RECEIVED OF Male Cenate Co. FEE OF S	5.
FOR WHICH PERMISSION IS GRANTED & with shop	
TO TAP Sanitary SEWER ON THE West	
of Jel. W. AVE. TYPE OF STREET March Kingar	_
THE PREMISES BEING LOT NO. 476-471-473 HOUSE NO. 725-71/ain	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUN OF THE DEPARTMENT OF PUBLIC SERVICE.	CIL, ANI

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.

Hole Conch. Co.