Stam

## Nº 8133

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

1-11-1-4	
DATE INSPECTED 4-11-69	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2757	
HOUSE NO.	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
	The state of the s
WAS LATERAL AT CURB?	$\overline{}$
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Alling to be leaven
SHOW BY DIAGRAM RELATION OF L	ATERAL TO WALL OF BUILDING SERVED.
(x,y) = (x,y) = (x,y) + (y,y) = (x,y) = (x,y	grafia de la compansión d
1 1/200	
1.HOUS	LINE RAN FROM N. CORN. OF A
	INTO CATCH BASIN
	<b>)</b> ,
	ECATEN Edsin
	and the state of t
100	
SIGNED WM. The December	FILED AT ENGINEER'S OFFICE

Stein

## $N^{\circ}$ 8133

NAME OF CONTRACTOR

## PERMIT TO TAP SEWER

4	Massilli	ON, OHIO, JUNE	3	
RECEIVED OF Blick of 71	caner		FFF OF S	5. 1
	yh Data	the		
TO TAR Warm	CEWED ON TH	South		
Schuler a.m. 71.71.	AVE.	Geare	C	-
1			57	
WORK TO BE DONE IN ACCORDANCE WITH OF				IL, ANI
OF THE DEPARTMENT OF PUBLIC SERVICE.				
Albert Ge	lick			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.