Nº 8152

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	·
DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 808 - 10	
SIZE OF PIPE USED 611	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 136 SOUTH OF MY A
WAS LATERAL AT CURB? NO	
WAS ATTACHED TO MAIN VES	NAME OF CONTRACTOR K. MARKS
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
N	7
<u></u>	7'P (94'
	- 136
SIGNED V CALARY INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE
DEMARKS	

Nº 8152

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	Massillon,	OHIO, JULY	3/
RECEIVED OF RECEIVED OF	MARKS		FEE OF S
		BLOG. INC.	
JA A/	SEWER ON THE_	E957	
2770 JT. N.Co.			en C
THE PREMISES BEING LOT NO. 13037	7	HOUSE NO. 508	5800
WORK TO BE DONE IN ACCORDANCE WITH ORDER OF THE DEPARTMENT OF PUBLIC SERVICE.	nance No. 2323, d	ULY PASSED BY THE C	ITY COUNCIL, ANI
NAME OF CONTRACTOR ROSTOR A	MARKS		٠.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.