Nº 8185

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-3-69	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED 411	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB7	en e
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR HOLDIER BAUM
SHOW BY DIAGRAM RELATION OF LATER	l i
	1 1 1 P1P
SIGNED INSPECTOR FOR CITY	FILED AT ENGINEER'S OFFICE
REMARKS No MICA	1 HIS STYLET

Relay

## Nº 8185

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

And the state of t	MASSILLON, OHIO,	evenlue 2
RECEIVED OF State	lderbaum	FEE OF \$ 5
FOR WHICH PERMISSION IS GRA	NTED Carlinter	
TO TAP Sanctar	sewer on the Dan	th
of Shack Pl	J.W. AVE. ST. TYPE OF STREET	wel Chip of le.
THE PREMISES BEING LOT NO	9351 HOUSE NO.	631-June
WORK TO BE DONE IN ACCORDA	ANCE WITH ORDINANCE No. 2323, DULY PASSED IC SERVICE.	BY THE CITY COUNCIL, ANI
NAME OF CONTRACTOR	elde haven	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.