$\sqrt{}$ Following data to be answered by inspector and signed when returned

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	/ b/
HOUSE NO	DISTANCE FROM FIRST MANHOLE	, 15
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	<u> </u>
WAS LATERAL AT CURB? Peparing	o de la companya di santana di sa Tanàna di santana di s	, A ^N
WAS ATTACHED TO MAIN No	NAME OF CONTRACTOR Nacto	dishacien ?
/1	**************************************	29-
A MAN THE RESERVE AND A STATE OF A STATE OF THE STATE OF	 State of the control of	tt name Commen
		Nicurn
		NILLAMS
SIGNED INSPECTOR FOR CI	FILED AT ÉNGINEER'S	
REMARKS	n .	

Relay Nº 8189

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	. Massillon,	OHIO James and	<u> </u>
RECEIVED OF Afald	lebaum-		FEE OF \$
FOR WHICH PERMISSION IS GRANTED.	Mrs 711-6 71-	elty	i .
TO TAP Sanitary	SEWER ON THE	West	_
of 11# 18.71.6.	AVE. ST. TYPE OF STREET	Hard den	face
THE PREMISES BEING LOT NO.	2/3	HOUSE NO. 105	2 Willian
· · · · · · · · · · · · · · · · · · ·			

Heldicknene

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.