

No 8192

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-18-70IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 437SIZE OF PIPE USED 6" 4"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 152'WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR MARICS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

RELAY

4" X WITH 1 LINE
GOING TO CELLAR AND
1 LINE GOING TO UPPIERS
2' DEEP

6" TO 4"
REDUCER & D



10' 4"

SIGNED

R. J. Hall

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

6" 30° 1
4' DE

Relay
Nº 8192

10 -
OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Feb. 18*
RECEIVED OF *Roscoe Marks* FEE OF \$ *5.*
FOR WHICH PERMISSION IS GRANTED *William Lucker*
TO TAP *Sanitary* SEWER ON THE *West*
OF *17th St. N.W.* AVE. *Chipp & Lusk*
ST. TYPE OF STREET
THE PREMISES BEING LOT NO. *5069* HOUSE NO. *437*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Roscoe Marks*

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.