

No 8193

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2-18-70IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____HOUSE NO. 442SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH N/AWAS LATERAL AT CURB? N/A


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR HOLDERBAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

RELAY

PUT IN 6" PIPE
(VERTICAL) FOR
CLEAN OUT. LATERAL
IS 3 FEET DEEP



SIGNED

Ronald L. Hatten

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Relay

Nº 8193

2
OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Feb. 18* 1

RECEIVED OF *Haldichaux* FEE OF \$ *5.*

FOR WHICH PERMISSION IS GRANTED *Ray Wentzel*

TO TAP *Sanitary* SEWER ON THE *East*

OF *6th Lt. W.E.* AVE. ST. TYPE OF STREET *Asphalt*

THE PREMISES BEING LOT NO. *854* HOUSE NO. *442*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Haldichaux*

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.