FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED _ 4-16-70	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	771560THOSM
HOUSE NO. 1303		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? No	e de la companya del companya de la companya de la companya del companya de la co	to produce the second
WAS ATTACHED TO MAIN NO /N	STYPET NAME OF CONTRACTOR	D. ROGERS
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED	•
and the second s		18
	A Committee Comm	5
The manager of the second control of the sec		34/
	<u> </u>	4 W. Cu
	<u> </u>	35242
	· · · · · · · · · · · · · · · · · · ·	77'
SIGNED V. Vatham	FILED AT ENGINEE	R'S OFFICE
INSPECTOR FOR CIT		* Ter gift gar
REMARKS	* ·	

7-46
OFFICE OF THE DIRECTOR OF PUBLIC SEI

N 8201

PERMIT TO TAP SEWER

_	Massillon,	OHIO, April	10
RECEIVED OF Dale Ro	rgero		FEE OF \$ 5.
FOR WHICH PERMISSION IS GRANTED Metry	politan (meh. Co.	
TO TAP Canitary	_SEWER ON THE	Meet	
of Johnson Il S.G. AVE	TYPE OF STREET	Chis & lead	0/1
THE PREMISES BEING LOT NO. 5442		HOUSE NO. 130 3	3

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR TAGEL

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.