Nº 8203

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-16-70	IF SO HOW AND LOCATION FROM 45 EAST OF MA 5 1
HOUSE NO. 49 SIZE OF PIPE USED 4" WAS LATERAL AT CURB? NO	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR M. HOLDE BAUM ERAL TO WALL OF BUILDING SERVED. 9/8/P
	RELAID
SIGNED V. Katham	5. CURB SD. TILED AT ENGINEER'S OFFICE 1 45' -
INSPECTOR FOR CIT	

Relay

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, Afril 13
RECEIVED OF Hilderbaum	ve 5.
FOR WHICH PERMISSION IS GRANTED Hitheit	nko
TO TAP anclary SE	South !
Reach and S.E. AVE.	· · · · · · · · · · · · · · · · · · ·
THE PREMISES BEING LOT NO. 3883	HOUSE NO. 49
	E No. 2323, DULY PASSED BY THE CITY COUNCIL, AND

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, ANI OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Haldulaum

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.