

STORM

Nº 8204

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1201-19

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED _____

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Storm
Nº 8204

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, *April* 13 1
RECEIVED OF *Halderbaum* FEE OF \$ *5.*
FOR WHICH PERMISSION IS GRANTED *Baptist Temple*
TO TAP *Storm* SEWER ON THE *South*
OF *Amesbury Ave. S. W.* AVE. *Chip & Seal*
ST. TYPE OF STREET
THE PREMISES BEING LOT NO. *O. H. 288* HOUSE NO. *1201-19*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Halderbaum*

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.