## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED JULY 2 1970	IF SO HOW AND LOCATION FROM 208
SIZE OF PIPE USED G	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR SCHUMACHER
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SERVED.
	8,7
n de la composition della comp	818 0
SIGNED INSPECTOR FOR CITY	-J08

Umil.

## Nº 8222

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	0 0 1	7 /) MA59	ILLON, OHIO,	cly 1	
RECEIVED OF_	Le Ray &	chima	Aus	FEE C	, A
FOR WHICH PERMISSIO	N IS GRANTED	Royd	of character	7	· •
<i>t</i> •	lary	SEWER ON	ITHE Case	<i>f</i>	
Parkain	MIE mil =		Chin	K. K. Lik	
THE PREMISES BEING I	.ot No		, HOUSE NO.	940	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR SCHOOL SHEET

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.