## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-20-76	IF SO HOW AND LOCATION FROM 103	
HOUSE NO. 999		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	
WAS LATERAL AT CURB? No	- Constitution of the Cons	-
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR DIANA	
SHOW BY DIAGRAM RELATION OF LAT		
	4. DEELS	٤.
	1 8 N	
	1. The contraction of the contra	
	Jaco	
P 00 2/41	a-103-pj464'-p	
SIGNED INSPECTOR FOR C		
	ACING WRONG DIRECTION, HAD TO BE TO	JICN E L
AROUND TO FACE SOUTH,		4

## Nº 8237

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO Luguet	4
RECEIVED OF A. M. Cand	MASSILLON, OHIO	5.
FOR WHICH PERMISSION IS GRANTED A. DI.	Some Co.	
TO TAP Sanctary SEWE	ER ON THE South	
Oblilie PH. S. W. AVE. TYPE	OF STREET Chip & Le	<u> </u>
THE PREMISES BEING LOT NO. O. 1. 287	HOUSE NO. 99	9
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE !	No. 2323, DULY PASSED BY THE CIT	Y COUNCIL, ANE

NAME OF CONTRACTOR A. L. Kreand

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.