Kelaj

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DAT	E INSPECTED 8-12-70	IF SO HOW AND LOCATION FROM	
ноц	JSE NO. 302 - 306	FIRST MANHOLE DOWN STREAM	÷
	E OF PIPE USED 6 "	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS	S LATERAL AT CURB?	The state of the s	4
WAS	SATTACHED TO MAIN	NAME OF CONTRACTOR HOLDER BRUM	Λ
SHC	W BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED.	₹
	and the state of t	6"	SADDLE 45 DECP
		The state of the s	
	R 11-11/4	4	
SIGN	NED INSPECTOR FOR C	FILED AT ENGINEER'S OFFICE	
REM	IARKS		

Relag

Nº 8241

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

RECEIVED OF	Holder	Massillon, C	DHIO August 12
FOR WHICH PERMISSION IS	GRANTED July		Enger (Olds)
OF_Cit At.	M- AVE.	YPE OF STREET	Hard Sugace
THE PREMISES BEING LOT	vo	, Н	OUSE NO. 302- 1306

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Halfur aum

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.