No. 8244 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED AND SIGNED WHEN RETURNED

DATE INSPECTED 7-31-7	IF SO HOW AND LOCATION FROM FASTALLIED VVI 123 FAS
HOUSE NO. 23/6-18	not,
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBY NO	orania. Programa de la compansión de la com Transportación de la compansión de la comp
WAS ATTACHED TO MAIN 15	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED.
Maria Rep. No.	in the state of th
	30 85 10
	The state of the s
	(-123' -> 28')
097	
SIGNED NOTICE INSPECTOR FOR	FILED AT ENGINEER'S OFFICE

North

N° 8244

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

RECEIVED OF MASSILLON, OHIO Ling. 27 RECEIVED OF MASSILLON, OHIO LING. 27 FEE OF S. 5.
FOR WHICH PERMISSION IS GRANTED # 21 711- Novall
TO TAP Sanctary SEWER ON THE MAIL
M-Londolla J.E. AVE. ST. TYPE OF STREET Chip & L.C.
THE PREMISES BEING LOT NO. 13461 HOUSE NO. 2316-2318

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Hawket

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.