

3

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

Nº 8253

DATE INSPECTED 9-15-70

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

HOUSE NO. 211

SIZE OF PIPE USED 4"



DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

WAS LATERAL AT CURB? Repaired in street

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR R. Marks

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

L. Latham  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

*Relay J*  
No 8253

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS  
PERMIT TO TAP SEWER

MASSILLON, OHIO.

*September 15* 19*11*

RECEIVED OF

*Racee Marks*

FEE OF \$ *5.*

FOR WHICH PERMISSION IS GRANTED

*Frank Falty*

TO TAP

*Sanitary*

SEWER ON THE

*South*

OF

*Commonwealth*

AVE.

ST. TYPE OF STREET

*Hard Surface*

THE PREMISES BEING LOT NO.

*4850*

HOUSE NO.

*211*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

*Marks*

Note: This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.