FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2609-11		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH CURB LINE AND DEPTH	4 75
WAS LATERAL AT CURB? VES	$A \cap C$	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	NA
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.	16
		E30°BEND
the management of the state of	A STATE OF THE STA	960
	€16 →	
		
SIGNED INSPECTOR FOR CI	FILED AT ENGINEER'S OFFICE	
INSPECTOR FOR CI		

208/

Nº 8263

PERMIT TO TAP SEWER

MASSILLON, OHIO, HOTHINGE /4			
RECEIVED OF James Thiken FEE OF \$ 5.			
James of Robert Jong			
FOR WHICH PERMISSION IS GRANTED			
TO TAP SEWER ON THE SAUCH			
of the One. 77 90. AVE. ST. TYPE OF STREET. Chip of Leal			
THE PREMISES BEING LOT NO. 12890 , HOUSE NO. 2609 - 2611			
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, ANI OF THE DEPARTMENT OF PUBLIC SERVICE.			
Marie			
NAME OF CONTRACTOR			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.