Nº 8264 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-1-70 HOUSE NO. 15-28 Through	IF SO HOW AND LOCATION FROM TAPPEd with Stant FIRST MANHOLE DOWN STREAM CIff East of up Stream in
SIZE OF PIPE USED C'	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? No	NAME OF CONTRACTOR ADIANA
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED.
	16
SIGNED A INSPECTOR FOR	FILED AT ENGINEER'S OFFICE

6 opto

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

A	MASSILLON, OHIO, MASSILLON 18
RECEIVED OF LAMES Z	leken 5.
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	es theken
TO TAP & ametary	Worth
alukum and IIIV AVE.	Chy & Lice
P.Y. C.h. 12	1 15 28 many 15 3
THE PREMISES BEING LOT NO.	HOUSE NO. 2323, DULY PASSED BY THE CITY COUNCIL, ANI

Note: This permit covers work outside of building only. Any work

OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTO

walls of building is subject to Massillon Board of Health Regulations.