REMARKS .

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 8266 AND SIGNED WHEN RETURNED

DATE INSPECTED 4-23-7/ HOUSE NO. 2409# 11	IF SO HOW AND LOCATION FROM 67 EAST of My
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? No	NAME OF CONTRACTOR Howbet
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.
	7p > 16 67
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE

Righty

Nº 8266

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSIELON, OHIO Hemollin 18
RECEIVED OF Gampet	FEE OF \$ 5.
FOR WHICH PERMISSION IS GRANTED	11 Lonald, Due.
TO TAP Samitary 5	EWER ON THE Sact
of Mc Sould de A.E. AVE. ST. T.	YPE OF STREET Chip & Lace
THE PREMISES BEING LOT NO. 13 46 9	HOUSE NO. 2409-2411

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, ANI OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Manuful

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.