

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 12-10-70

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM STUB. IN MH 3' DEEP

HOUSE NO. 316 & 18


SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR How BRET Con

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____ FILED AT ENGINEER'S OFFICE _____
INSPECTOR FOR CITY

REMARKS From Curb to MH Lateral incased in Concrete
NOT ENOUGH COVER IN ROADWAY

Duplex

Nº 8267

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO *November 18*

RECEIVED OF *Hawth* FEE OF \$ *5.*

FOR WHICH PERMISSION IS GRANTED *Wm M. Donald, Inc.*

TO TAP *Sanitary* SEWER ON THE *East*

OF *24th St. S.E.* AVE. ST. TYPE OF STREET *Chip & Seal*

THE PREMISES BEING LOT NO. *13468*, HOUSE NO. *316-318*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Hawth*

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.