	$\sqrt{}$ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR ${f N}^{ m o}$ 8268 AND SIGNED WHEN RETURNED
	AND SIGNED WHEN RETURNED DATE INSPECTED 12-10-70 IF SO HOW AND LOCATION FROM STOB IN MAY FIRST MANHOLE DOWN STREAM STOB IN MAY 3 DATE HOUSE NO. 315 \$ 17
	SIZE OF PIPE USED C C DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
	WAS LATERAL AT CURB? NO
	SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
	20
	3'DP Co
j	25'
ari ata	SIGNED INSPECTOR FOR CITY FILED AT ENGINEER'S OFFICE
	REMARKS Form Curb to M halyal incased in Concrete
	NOT ENOUGH COVER IN ROADWAY

Duply

N $^{\circ}$ 8268

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, Worker 18		
Kombet	MASSILLON, OHIO,		
Wed M.	Clarald Dire.		
FOR WHICH PERMISSION IS GRANTED			
	VER ON THE WAT		
OF 24 # 11 TIE. AVE. TYP	e of Street Chip & Seel		
THE PREMISES BEING LOT NO. 13 46 7	HOUSE NO. 315-317		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	No. 2323, DULY PASSED BY THE CITY COUNCIL, AND		

Name of Company Hawket

OF THE DEPARTMENT OF PUBLIC SERVICE.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.