REMARKS

N° Following data to be answered by inspector and signed when returned

	DATE INSPECTED /2-/7-7 0	IF SO HOW AND LOCATION FROM WYE	245 East JM 9
4	HOUSE NO. 2033 & 35		
	C (DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
	WAS LATERAL AT CURB? NG	in the second of	
	\\\ \	NAME OF CONTRACTOR	Valentine
	SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SERVED.	1
		· · · · · · · · · · · · · · · · · · ·	8
	en e	entropy of the second of the s	66 X 977
		· · · · · · · · · · · · · · · · · · ·	5' 2'
	SIGNED & Sathan	FILED AT ENGINEER	S OFFICE (75' ->
	INSPECTOR FOR CITY		

Duply

N? 8272

PERMIT TO TAP SEWER

MASS	ILLON, OHIO, Moneralue 23
RECEIVED OF Talinant 6 pear	sting FEE OF S.
	Tedelyus, Inc.
TO TAP SEWER ON	- Donath
Mariachusetto St. AVE. ST. TYPE OF S.	TREET Chiz & LeC
THE PREMISES BEING LOT NO. $6333-6333$	HOUSE NO. 2033-2035

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AN OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR & Colonbuck

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.