

NO. 8284 ✓

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-11-71

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM INSTALLED WYE 21ft. east

HOUSE NO. 1825

SIZE OF PIPE USED _____


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR A. Glick

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED S. Latham
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 8284 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO

March 9

RECEIVED OF

Albert Glick

FEE OF \$ 5.

FOR WHICH PERMISSION IS GRANTED

Don Johns

TO TAP

Sanitary

SEWER ON THE

In Circle

OF

Dexter Rd. H.C.

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

11561

HOUSE NO.

~~1253~~ 182

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Albert Glick

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.